

historic resources survey

site no. 317

FOR OFFICE USE ONLY			
TOWN NO.:	SITE NO.:		
UTM: 18/	/	/	/
QUAD:			
DISTRICT:	S	NR:	ACTUAL POTENTIAL

715 main street willimantic, ct. 06226

IDENTIFICATION

1. BUILDING NAME: Common: residence Historic: Jone, Eliakim, House
2. TOWN/CITY: _____ VILLAGE: Mewow COUNTY: _____
3. STREET & NUMBER (and/or location): 1673 Stafford Rd
4. OWNER(S): _____ PUBLIC / PRIVATE
5. USE: Present: residence Historic: _____
6. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: yes no
Interior accessible: yes, explain no

DESCRIPTION

7. STYLE OF BUILDING: Greek Revival DATE OF CONSTRUCTION: c 1830
8. MATERIAL(S) (indicate use or location when appropriate):
 clapboard asbestos siding brick
 wood shingle asphalt siding fieldstone
 board & batten stucco cobblestone
 aluminum siding concrete: type: _____ cut stone: type: _____
 other: _____
9. STRUCTURAL SYSTEM:
 wood frame: post and beam balloon
 load bearing masonry structural iron or steel
 other: _____
10. ROOF: type:
 gable flat mansard monitor sawtooth
 gambrel shed hip round other _____
material:
 wood shingle roll asphalt tin slate
 asphalt shingle built up tile other: _____
11. NUMBER OF STORIES: 2 APPROXIMATE DIMENSIONS: _____
12. CONDITION: Structural: excellent good fair deteriorated
Exterior: excellent good fair deteriorated
13. INTEGRITY: Location: on original site moved, when: _____
Alterations: no yes, explain: sash, rear addition
14. RELATED OUTBUILDINGS OR LANDSCAPE FEATURES:
 barn shed garage other landscape features or buildings: _____
 carriage house shop garden
15. SURROUNDING ENVIRONMENT:
 open land woodland residential scattered buildings visible from site
 commercial industrial rural high building density
16. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
compatible

17. OTHER NOTABLE FEATURES OF BUILDING OR SITE (interior and/or exterior):

- ① balanced 9-window facade
- ② corner pilasters w/ triglyphs above capital
- ③ fully pedimented gable end w/ modillions, hemispheric light in tympanum
- ④ 4/6 sash, appears new
- ⑤ entry framed by two pair of pilasters on either side of 3/3 sidelights, full entablature above
- ⑥ concrete foundation, new

SIGNIFICANCE

Architect: _____ Builder: _____

18. HISTORICAL OR ARCHITECTURAL IMPORTANCE:

① large lean-to rear addition w/ shed roof springing from ridge line

House extensively restored & added to recently. The lean-to addition is new. There was an ell, which was probably the original house; it was demolished sometime after 1942, but the foundation was clearly visible in 1963. MHS has pictures.


PHOTOGRAPH

photographer: JD
date: 9/78 view: North, entry detail
negative on file: _____

COMPILED BY:

name: _____ date: _____
organization: _____
address: _____

19. SOURCES:



20. SUBSEQUENT FIELD EVALUATIONS:

21. THREATS TO BUILDING OR SITE:

none known highways vandalism developers other: _____
 renewal private deterioration zoning explanation: _____